

NEEDS ASSESSMENT REPORT OF LEA BAUDA, BARKIN LADI LGEA. AUGUST 2024.

INSUFFICIENT CLASSROOMS IN THE SCHOOL.

NEED

TO BUILD NEW CLASSROOMS

- I. EXCAVATION OF FOUNDATION TRENCHES
- II. FOUNDATION WORK (INCLUDING RAMP)
- III. BLOCKWORK TO ROOFING LEVEL
- IV. CONCRETE COLUMNS AND BEAMS IN VERANDAH
- V. WOOD WORK ON ROOF
- VI. ROOFING SHEETS (0.55MM GAUGE STONE COATED ALUMINIUM)
- VII. FIXING OF METAL DOORS AND WINDOWS
- VIII. NEW PLASTERING
- IX. TERRAZZO FLOORING
- X. PAINTING
- XI. SOLAR INSTALLATIONS

PROGRESS PICTURES



NEEDS ASSESSMENT REPORT OF LEA RAMBU, BARKIN LADI LGEA. AUGUST 2024.

INSUFFICIENT CLASSROOMS IN THE SCHOOL.

NEED

TO BUILD NEW CLASSROOMS

- I. EXCAVATION OF FOUNDATION TRENCHES
- II. FOUNDATION WORK (INCLUDING RAMP)
- III. BLOCKWORK TO ROOFING LEVEL
- IV. CONCRETE COLUMNS AND BEAMS IN VERANDAH
- V. WOOD WORK ON ROOF
- VI. ROOFING SHEETS (0.55MM GAUGE STONE COATED ALUMINIUM)
- VII. FIXING OF METAL DOORS AND WINDOWS
- VIII. NEW PLASTERING
- IX. TERRAZZO FLOORING
- X. PAINTING
- XI. SOLAR INSTALLATIONS

PROGRESS PICTURES



NEEDS ASSESSMENT REPORT OF LEA MAZAT, BARKIN LADI LGEA. AUGUST 2024.

INSUFFICIENT CLASSROOMS IN THE SCHOOL.

NEED

TO BUILD NEW CLASSROOMS

- I. EXCAVATION OF FOUNDATION TRENCHES
- II. FOUNDATION WORK (INCLUDING RAMP)
- III. BLOCKWORK TO ROOFING LEVEL
- IV. CONCRETE COLUMNS AND BEAMS IN VERANDAH
- V. WOOD WORK ON ROOF
- VI. ROOFING SHEETS (0.55MM GAUGE STONE COATED ALUMINIUM)
- VII. FIXING OF METAL DOORS AND WINDOWS
- VIII. NEW PLASTERING
- IX. TERRAZZO FLOORING
- X. PAINTING
- XI. SOLAR INSTALLATIONS

PROGRESS PICTURES



NEEDS ASSESSMENT REPORT OF LEA HURUM-GASHISH, BARKIN LADI LGEA. AUGUST 2024.
INSUFFICIENT CLASSROOMS IN THE SCHOOL.

NEED

TO BUILD NEW CLASSROOMS

- I. EXCAVATION OF FOUNDATION TRENCHES
- II. FOUNDATION WORK (INCLUDING RAMP)
- III. BLOCKWORK TO ROOFING LEVEL
- IV. CONCRETE COLUMNS AND BEAMS IN VERANDAH
- V. WOOD WORK ON ROOF
- VI. ROOFING SHEETS (0.55MM GAUGE STONE COATED ALUMINIUM)
- VII. FIXING OF METAL DOORS AND WINDOWS
- VIII. NEW PLASTERING
- IX. TERRAZZO FLOORING
- X. PAINTING
- XI. SOLAR INSTALLATIONS

PROGRESS PICTURES



NEEDS ASSESSMENT REPORT OF LEA NTV II, BARKIN LADI LGEA. AUGUST 2024.

INSUFFICIENT CLASSROOMS IN THE SCHOOL.

NEED

TO BUILD NEW CLASSROOMS

- I. EXCAVATION OF FOUNDATION TRENCHES
- II. FOUNDATION WORK (INCLUDING RAMP)
- III. BLOCKWORK TO ROOFING LEVEL
- IV. CONCRETE COLUMNS AND BEAMS IN VERANDAH
- V. WOOD WORK ON ROOF
- VI. ROOFING SHEETS (0.55MM GAUGE STONE COATED ALUMINIUM)
- VII. FIXING OF METAL DOORS AND WINDOWS
- VIII. NEW PLASTERING
- IX. TERRAZZO FLOORING
- X. PAINTING
- XI. SOLAR INSTALLATIONS

PROGRESS PICTURES



NEEDS ASSESSMENT REPORT OF LEA FAN-LOH, BARKIN LADI LGEA. AUGUST 2024.
DILAPIDATED STANDARD MUD CLASSROOMS IN THE SCHOOL.

NEED

TO RENOVATE A BLOCK OF FOUR CLASSROOMS

- I. REMOVAL OF ROOF STRUCTURE
- II. PULLING DOWN OF WEAK WALLS
- III. SCRAPING OF WEAK PLASTER
- IV. BLOCKWORK TO ROOFING LEVEL
- V. CONCRETE COLUMNS AND BEAMS IN VERANDAH
- VI. WOOD WORK ON ROOF
- VII. ROOFING SHEETS (0.55MM GAUGE STONE COATED ALUMINIUM)
- VIII. FIXING OF METAL DOORS AND WINDOWS
- IX. PLASTERING
- X. SCREED FLOORING
- XI. PAINTING

PROGRESS PICTURES



NEEDS ASSESSMENT REPORT OF LEA BEK, BARKIN LADI LGEA. AUGUST 2024.

DILAPIDATED STANDARD CLASSROOMS IN THE SCHOOL.

NEED

TO RENOVATE A BLOCK OF TWO CLASSROOMS/OFFICE/ STORE

- I. REMOVAL OF ROOF STRUCTURE
- II. SCRAPE WEAK PLASTER
- III. BLOCKWORK TO ROOFING LEVEL
- IV. CONCRETE COLUMNS AND BEAMS IN VERANDAH
- V. WOOD WORK ON ROOF
- VI. ROOFING SHEETS (0.55MM GAUGE STONE COATED ALUMINIUM)
- VII. FIXING OF METAL DOORS AND WINDOWS
- VIII. PLASTERING
- IX. SCREED FLOORING
- X. PAINTING

PROGRESS PICTURES



NEEDS ASSESSMENT REPORT OF LEA MAI IDON TARO, BARKIN LADI LGEA. AUGUST 2024.
DILAPIDATED STANDARD CLASSROOMS IN THE SCHOOL.

NEED

TO RENOVATE A BLOCK OF THREE CLASSROOMS

- I. REMOVAL OF ROOF STRUCTURE
- II. SCRAPING OF WEAK FLOOR AND PLASTER
- III. BLOCKWORK TO ROOFING LEVEL
- IV. CONCRETE COLUMNS AND BEAMS IN VERANDAH
- V. WOOD WORK ON ROOF
- VI. ROOFING SHEETS (0.55MM GAUGE STONE COATED ALUMINIUM)
- VII. FIXING OF METAL DOORS AND WINDOWS
- VIII. PLASTERING
- IX. SCREED FLOORING
- X. PAINTING

PROGRESS PICTURES



NEEDS ASSESSMENT REPORT OF LEA SHUMON, BARKIN LADI LGEA. AUGUST 2024.
DILAPIDATED STANDARD MUD CLASSROOMS IN THE SCHOOL.

NEED

TO RENOVATE A BLOCK OF THREE CLASSROOMS

- I. REMOVAL OF ROOF STRUCTURE
- II. SCRAPING OF WEAK FLOOR AND PLASTER
- III. BLOCKWORK TO ROOFING LEVEL
- IV. CONCRETE COLUMNS AND BEAMS IN VERANDAH
- V. WOOD WORK ON ROOF
- VI. ROOFING SHEETS (0.55MM GAUGE STONE COATED ALUMINIUM)
- VII. FIXING OF METAL DOORS AND WINDOWS
- VIII. PLASTERING
- IX. SCREED FLOORING
- X. PAINTING

PROGRESS PICTURES

